



August 2th, 2021

About: FrieslandCampina Lattiz® machine – New air pump

2 augustus 2021

*Betreft: FrieslandCampina Lattiz® machine – Nieuwe luchtpomp
zie pagina 2*

Dear Lattiz partner,

We would like to inform you that the air pump for all Lattiz machines is replaced for a new item. The reason for this change is that the supplier has taken the old air pump out of the assortment and it's therefore no longer available. The mechanical characteristics of the new air pump remains and does not affect the performance and both the article number and price remain the same.

Art. No.	Description
1004600	PUMP AIR WITH NOISE REDUCTION

This change is implemented from machine number **1032107054**. Also with all new spare part orders we will deliver the new model (see picture).

This new air pump is fully backwards compatible. Existing spare parts on stock (old version, same Art. No.) can still be used for all machines Lattiz. There is no need to replace the current air pump, as it does not affect the functionality of the machine.



We hope to have provided you with sufficient information. If you have any questions you can reach us by telephone or email.

With best regards,

Team Coffee First
+31 (0)85 – 760 28 48
support@coffeefirst.eu



Beste Lattiz partner,

Bij deze willen we u informeren dat de luchtpomp voor zowel Lattiz V1.x als Lattiz 2.0 is vervangen door een ander exemplaar. Deze aanpassing was nodig omdat het oude model bij de leverancier uit het assortiment is gehaald en daarom ook niet langer meer beschikbaar is. De werking is ongewijzigd en zowel het artikelnummer als de prijs blijft gelijk.

Artikelnr	Omschrijving
1004600	LUCHTPOMP MET GELUIDSREDUCTIE

Deze aanpassing is toegepast vanaf Lattiz 2.0 machines met serienummer **1032107054**. Ook zal vanaf heden bij iedere nieuwe onderdeelbestelling het model zoals op de afbeelding hiernaast geleverd worden.

De luchtpomp is volledig backwards compatibel. Bestaande voorraad (oude versie, zelfde artikelnummer) kunnen gewoon gebruikt worden voor alle Lattiz machines. Er is geen noodzaak om de bestaande luchtpomp te vervangen, dit heeft geen verdere invloed op de functionaliteit van de machine.



We hopen u hierbij voldoende te hebben geïnformeerd. Mocht u nog vragen hebben kunt u ons gewoon via telefoon of email bereiken.

Met vriendelijke groet,

Team Coffee First
+31 (0)85 – 760 28 48 (Kantoor)
support@coffeefirst.eu